

ANNUAL

Annual Playground Safety Inspection 2025

Greenfield Municipal Council

INSPECTOR James Mitchell	STANDARDS EN 1176, EN 1177, EN 16630	DATE 5/7/2025	SITES INSPECTED 3
------------------------------------	--	-------------------------	-----------------------------

Assessment Categories

Classification of findings based on safety impact level

CATEGORY	SAFETY IMPACT	EXAMPLES
A	None - fully compliant	No issues found
B	Minor - no direct safety impact	Missing signage, minor wear, faded markings, incomplete non-hazardous equipment
C	Medium - potential injury risk	Protruding bolts, incorrect clearances, surface depth issues, equipment gaps, corrosion
D	High - serious injury risk	Entrapment hazards, unsafe connections, visible structural decay, broken safety features

Important: A positive safety opinion is NOT issued if any Category C or D findings are present. All C and D issues must be resolved before the site can be certified as safe.



FACILITIES

- Lighting
- Fencing
- Seating
- Waste bin

EQUIPMENT

1. Swing set (4-seat) 2. Spring rocker - elephant 3. Climbing frame with slide 4. Sandbox 5. Seesaw 6. Picnic shelter

#	CRITERIA	CAT.	FINDINGS
1	Signage / regulations	B	Missing regulations sign
2	Surface condition	A	
3	Clearances	A	
4	Equipment stability	A	
5	Equipment completeness	C	Seesaw missing bumper (item 5)
6	Mechanical damage	B	Damaged fence panel (east side)
7	Connections / joints	C	Missing bolt - climbing frame (item 3, photo 3). Loose handle - spring rocker (item 2, photo 4)
8	Wood condition	D	Climbing frame (item 3) - visible rot on support beams (photo 5, photo 6)
9	Corrosion	A	
10	Sharp edges / rough surfaces	C	Protruding bolt heads - climbing frame (item 3, photo 3)

PHOTO EVIDENCE





FACILITIES

Lighting Fencing Seating Waste bin

EQUIPMENT

1. Swing set (2-seat) 2. Slide tower 3. Carousel 4. Balance beam 5. Sand table

#	CRITERIA	CAT.	FINDINGS
1	Signage / regulations	A	
2	Surface condition	A	
3	Clearances	A	
4	Equipment stability	A	
5	Equipment completeness	A	
6	Mechanical damage	A	
7	Connections / joints	A	
8	Wood condition	B	Minor surface rust on carousel bearing cover
9	Corrosion	A	
10	Sharp edges / rough surfaces		

PHOTO EVIDENCE





FACILITIES

Lighting Fencing Seating Waste bin

EQUIPMENT

1. Pull-up station 2. Parallel bars 3. Leg press 4. Cross trainer 5. Balance board 6. Sit-up bench

#	CRITERIA	CAT.	FINDINGS
1	Signage / regulations	B	Usage instructions partially faded
2	Surface condition	B	Minor wear on rubber tiles around pull-up station
3	Clearances	A	
4	Equipment stability	A	
5	Equipment completeness	B	Missing grip cover on cross trainer handle (item 4)
6	Mechanical damage	A	
7	Connections / joints	A	
8	Wood condition	A	
9	Corrosion	A	
10	Sharp edges / rough surfaces	A	

PHOTO EVIDENCE

